**FIG. 1**




FIG. 2

3/12




FIG. 3A








FIG. 3B

**FIG. 4**


**FIG. 5**

**FIG. 6**

**FIG. 7**

TIME	BTS 1 (D-RLP 1)	BTS 2 (D-RLP 2)	BTS 3 (D-RLP 3)
TIME T=0	$E_V(S) = 12$ $E_V(L) = 11$ $E_V(I) = 12$	$E_V(S) = 12$ $E_V(L) = 11$ $E_V(I) = 12$	
TIME T=1	$E_V(S) = 13$ $E_V(L) = 11$ $E_V(I) = 12$	$E_V(S) = 12$ $E_V(L) = 11$ $E_V(I) = 12$	
TIME T=2	$E_V(S) = 15$ $E_V(L) = 13$ $E_V(I) = 12$	$E_V(S) = 14$ $E_V(L) = 13$ $E_V(I) = 12$	$E_V(S) = 12$ $E_V(L) = 12$ $E_V(I) = 12$
TIME T=3	$E_V(S) = 16$ $E_V(L) = 14$ $E_V(I) = 12$	$E_V(S) = 15$ $E_V(L) = 14$ $E_V(I) = 12$	$E_V(S) = 15$ $E_V(L) = 14$ $E_V(I) = 12$
TIME T=4	$E_V(S) = 20$ $E_V(L) = 19$ $E_V(I) = 12$	$E_V(S) = 23$ $E_V(L) = 19$ $E_V(I) = 12$	$E_V(S) = 20$ $E_V(L) = 19$ $E_V(I) = 12$
TIME T=5	$E_V(S) = 22$ $E_V(L) = 21$ $E_V(I) = 12$	$E_V(S) = 24$ $E_V(L) = 21$ $E_V(I) = 12$	$E_V(S) = 22$ $E_V(L) = 21$ $E_V(I) = 12$
TIME T=6	$E_V(S) = 22$ $E_V(L) = 21$ $E_V(I) = 22$	$E_V(S) = 24$ $E_V(L) = 21$ $E_V(I) = 22$	$E_V(S) = 22$ $E_V(L) = 21$ $E_V(I) = 22$

FIG. 8

**FIG. 9**

10/12




FIG. 10

11/12




FIG. 11

12/12




FIG. 12